

Subject: Velocity HP1000 Lamp Life Number: SRV0033

Applicability: All Velocity HP1000 Models Date: 05/07/08

Symptoms: Excessive Lamp issues, low lamp life with aftermarket lamps

Explanation: The ETS Velocity HP1000 has only been tested and certified to use

Heraeus OH N 50/100 EF 1000W high-pressure lamps. The effectiveness and life of aftermarket or alternative lamps cannot be

guaranteed or warranted by ETS.

Solution: When replacing lamps, only use the above certified high-pressure

lamp.

**NOTICE:** This document and the information disclosed herein are proprietary data of **ETS**, **LLC**. Neither this document nor the information contained herein shall be used, reproduced, or disclosed to others without the written authorization of **ETS**, **LLC**. except to the extent required for installation or maintenance of the recipient's equipment.

**CAUTION: ETS, LLC. Service Bulletins** are intended for use by experienced service technicians. They are written to inform those technicians of conditions that may occur in some equipment, or to provide information that could assist in the proper servicing of the equipment. If a condition is described, DO NOT assume that this service bulletin applies to your equipment, or that your equipment will develop that condition. Always consult your **ETS, LLC. Service Technician** before performing any modifications to your equipment. When electrical service is needed, we recommend hiring a professional electrician.

Bulletin Number: SRV0033 - Date: 05/08/08 Page 1 of 1