



# SERVICE BULLETIN

**Subject:** Canopy Handle Re-mounting

**Number:** SRV0010

**Applicability:** SUNVISION Elite 28/30/32  
SunStar ZX30  
SunStar ZX32 (pre 2001)

**Date:** 3/7/2005

**Symptoms:** Canopy handle will not mount securely or becomes loose from usage.

**Explanation:** Holes in aluminum extrusion behind the plastic profile were drilled too large or usage of the handle has worked the screws loose.

**Solution:** Drill 0.136" holes (#29 drill. 1/8" may be too tight, 5/32" will be too loose.) 1/4" to the right or left of the existing holes and reattach the handle. If the screws are damaged, replace with #10 x 1" sheet metal screws. The legs on the handle will hide the old holes when reinstalled.

**NOTICE:** This document and the information disclosed herein are proprietary data of ETS, Inc. Neither this document nor the information contained herein shall be used, reproduced, or disclosed to others without the written authorization of ETS, Inc. except to the extent required for installation or maintenance of the recipient's equipment.

**CAUTION:** ETS, Inc. Service Bulletins are intended for use by experienced service technicians. They are written to inform those technicians of conditions that may occur in some equipment, or to provide information that could assist in the proper servicing of the equipment. If a condition is described, DO NOT assume that this service bulletin must be applied to your equipment, or that your equipment will develop that condition. Always consult your ETS, Inc. Technical Service Representative before performing any modifications to your equipment. When electrical service is needed, we recommend hiring a professional electrician.