

**Subject:** New Buckbooster Configuration

**Number:** SRV0032

**Applicability:** Units that require a Buckbooster to bring voltage within applicable range

**Date:** 05/07/08

**Symptoms:** n/a

**Explanation:** Opportunities existed in Buckboost transformer design

**Solution:** Buckbooster design will be transitioning. All 1.0 KVA and higher Buckboost transformers will come equipped with junction boxes on either side of the transformer (1.0 KVA complete will still be available). Flexible "pig tail" wires will no longer be used on ETS buckboost transformers.

For appropriate KVA size, please call ETS Technical Service 800.449.3605



**\*Note Graphic shows the booster with cover and right side plate off**

---

**NOTICE:** This document and the information disclosed herein are proprietary data of **ETS, LLC**. Neither this document nor the information contained herein shall be used, reproduced, or disclosed to others without the written authorization of **ETS, LLC**, except to the extent required for installation or maintenance of the recipient's equipment.

**CAUTION:** **ETS, LLC. Service Bulletins** are intended for use by experienced service technicians. They are written to inform those technicians of conditions that may occur in some equipment, or to provide information that could assist in the proper servicing of the equipment. If a condition is described, **DO NOT** assume that this service bulletin applies to your equipment, or that your equipment will develop that condition. Always consult your **ETS, LLC. Service Technician** before performing any modifications to your equipment. When electrical service is needed, we recommend hiring a professional electrician.